


All screen shots were done on battery power except next to last one which is on mains power. The last one is from my desktop computer. I moved the computer from the original spot thinking it might be picking up interference from another computer that has X10 RF receiver attached.


10 us/div x1 16.26 kS right front USB.


10  $\mu$ s/div x 16 16.26 kS 100% 32 of 32

A Auto DC B Off




None A DV 50% 0s





10  $\mu$ s/div x 1 16.26 kS 32 of 32 100%

A Auto DC B Off DC



None A 0 V 50% 0 s